

Issues

| # | Project | Tracker | Status | Priority | Subject | Assignee | Updated |
|-------|-------------------------|---------|----------|----------|---|----------------|---------------------|
| 8740 | uBoone Operations | Bug | Resolved | Urgent | Eliminate cause of Vole-like chirping occurring on most channels when HV wire bias is turned on | Michael Mooney | 10/22/2015 12:51 PM |
| 10527 | uBooNE Detector Physics | Task | Resolved | Normal | Technotes: Space Charge Measurement | Michael Mooney | 11/10/2016 05:17 PM |